

**DS 4 选型表**

DS 4		[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]	[ ]		
测量压力	表压	6	8	0																		
额定量程	[bar]																					
	1.0				1	0	0	1														
	3.5				3	5	0	1														
	10				1	0	0	2														
	-1 ... 0				X	1	0	2												请咨询		
	用户需求				9	9	9	9													请咨询	
节点	1 节点							1														
	2 节点 <sup>1</sup>							2														
模拟输出	无模拟输出							0														
	1 ... 5 V / 3线制 <sup>1</sup>							C														
电气连接	M8x1 (4针)							Q	0	0												
	用户需求							9	9	9											请咨询	
压力接口及过程连接件	G1/8" 内螺纹							Q	0	0												
	M5 内螺纹带O型密封圈 <sup>2</sup>							R	0	0												
	用户需求							9	9	9											请咨询	
密封件	NBR																				5	
	用户需求																					9
参数设置	BD SENSORS 标准 <sup>3</sup>																					0 0 0
	按用户需求设置 <sup>3</sup>																					9 9 9
特殊型号	标准																					0 0 0
	用户需求																					9 9 9

<sup>1</sup> 可选模拟输出只能同时实现最多1个节点

<sup>2</sup> 可连接法兰

<sup>3</sup> 用户可通过以下设备编辑参数: 手操器 P6 和编程连接器 CIS Set (包括: 编程软件P-Set, 电脑连接器Adapt 3, 电源线以及电脑与压力开关接口连接线)  
手操器P 6 和 CIS Set 不包含在出货范围内, 订购时请另外订购, 详情参见相关产品样本

